

Symbols:



Screw holes for feedthrough
(<http://www.hubersuhner.com/ProdDet/3097269>)



M3 screw hole



Holes in top of lid serves both attachment to box body AND to plate

3D visualization:

