


▼ Multivariate

▼ Principal Components / Factor Analysis

▼ Principal Components: on Correlations

Number	Eigenvalue	Percent	20	40	60	80	Cum Percent
1	1.5862	39.654					39.654
2	1.2122	30.306					69.960
3	0.7820	19.550					89.510
4	0.4196	10.490					100.000

▼ Eigenvectors

Head IC	0.66989	-0.26665	0.03829	0.69186
Chest decel	0.70240	-0.07479	-0.03416	-0.70702
L Leg	0.16683	0.67653	0.71479	0.05964
R Leg	0.17335	0.68236	-0.69746	0.13374